## **Under Review Notification**

**Raised By:** <u>Steven Drouin</u> **Product #**: D205-634/D204-635/D209-669

Date: 17.05.16 Product Name: Skidtube

		"Y" or "N" Required for Each Part Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")	Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
D205-634-041/045	D205-634 Rev H	Υ	N	N	N	N	Y	Υ	569	CHG # Will be Affected
<del>D204-635-041</del>	D204-635 Rev G	Y	N	N	N	N	Y	Y	569	CHC # Will be Affected
D209-669-043	D209-669 Rev B	Υ	Ν	Ν	Ν	Ν	Υ	Υ	569	CHG # Will be Affected
D3564-1/-3/-5/-7/-11	D3564 Rev E	Y	N	N	N	N	N	N	569	
D3564-13/-15	D3564 Rev E	Y	N	N	N	N	N	N	<del>569</del>	

## Description of Issue:

Ok to ship D205-634-041/-045 change 005. New change number would required a DSI 9782-Ok to ship D204-635-041 change 005. New change number would required a DSI 9782-

Ok to ship D209-669-043 change 003. New change number would required a DSI 9782

**Distribution:** 

VP Operations
Director of Operations

Director Quality Assurance
Director of Engineering

Chief Engineer

Engineering Project Managers Engineering Clerk

Customer Support Manager

Production Engineers
Production Planners

Purchasing Manager Technical Support Product Manager - Solutions Provider